


CORNER RECORDDocument Number CR 6058City of OaklandCounty of Alameda, CaliforniaBrief Legal Description City of Oakland Monument.**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☒

Date of Survey January 15, 2014**COORDINATES (Optional)**

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH the position of an existing monument PRIOR to street or highway construction.

A description of the physical condition of the monument as found and as set or reset:

See sketch on back

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on January 16, 2014

Signed William Douglas Crume P.L.S. or R.C.E. No. LS 7059**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____
 and examined and filed _____

Signed Russell R. Penland P.L.S. or R.C.E. No. 5726Title COUNTY SURVEYOR

County Surveyor's Comment: _____

